Date:

Thursday, 17/07/2008 1:19:52 PM

Melanie Fauteux

Process Sheet

Customer

: CU-DAR001 Dart Helicopters Services

Job Number

Estimate Number

: 40593 : 13420

P.O. Number

This Issue

: 17/07/2008

: NC

S.O. No. :

: LARGE FAB ASSY Type

Part Number

Drawing Name

: PB6743001207

: SQUARE TUBE

Drawing Number

: B67,43001 P.5/ P.16

Project Number Drawing Revision : N/A : B1

Material

Due Date

: 24/07/2008

Qty:

Each

Previous Run Written By

Prsht Rev.

First Issue

Checked & Approved By Comment

: Est Rev:A

new issue DD verified by:ec

Additional Product

Job Number:



Seq. #:

Description:



6061T6 SQ TUBE 1.00 x 1.00 x .125w



Comment: Qty.:

1.9469 f(s)/Unit Total:

9.7346 f(s)

6061T6 SQ TUBE 1.00X.125

2.0

3.0

SMALL FAB



Comment: SMALL & MEDIUM FAB RESOURCE 1

1- cut to length as per dwg

2- make a 0.090" chamfer on both ends of tube

3- deburr

INSPECT WORK TO CURRENT S



Comment: INSPECT WORK TO CURRENT STEP



MILLING CONV

QC5

CONVENTIONAL MILLING MACHINE



Comment: CONVENTIONAL MILLING MACHINE

1- drill holes as per dwg

· 2- make a 0.090" chamfer (100 degree) on both side of the 4 holes

3- deburr

5.0

QC5

INSPECT WORK TO CURRENT STEP



Comment: INSPECT WORK TO CURRENT STEP



Thursday, 17/07/2008 1:19:52 PM Date: User: Melanie Fauteux **Process Sheet** Drawing Name: SQUARE TUBE Cristomer: CU-DAR001 Dart Helicopters Services Part Number: PB6743001207 Job Number: 40593 Job Number: Seq. #: Description: **Machine Or Operation:** PB6743001225 6.0 Bushing Comment: Qty.: 4.0000 Each(s)/Unit Total: 20.0000 Each(s) Bushing batch: 7.0 PB6743001223 Comment: Qty.: 1.0000 Each(s)/Unit Total: 5.0000 Each(s) Square Cap batch: 8.0 Comment: LARGE FABRICATION RESOURCE 1- Weld assembly as per dwg 9.0 SMALL FAB 1 Comment: SMALL & MEDIUM FAB RESOURCE 1 1- grind weld flush 2- deburr 10.0 QC10 Comment: VISUAL SPECTION OF GROUND WELDS INSPECT WORK TO CURRENT STEP 11.0 Comment: INSPECT WORK TO CURRENT STEP PACKAGING 1 12.0 PACKAGING RESOURCE #1 Comment: PACKAGING RESOURCE #1 Identify and Stock Location: W4 13.0 QC21 FINAL INSPECTION/W/O RELEASE Comment: FINAL INSPECTION/W/O RELEASE

Page 2

Form: rprocess

